

Zone 3B - North Shelly Beach



Present Issues

Key Actions



| | | |
|---|---|---|
| <div>Public views of the beach / ocean from the coastal path between William Street and the Creek / drain at northern end of Victoria Terrace highly valued as part of the coastal path experience.</div> <div>1</div> | <div>Maintain filtered views of the beach / ocean from the coastal path between William Street and the Creek / drain at northern end of Victoria Terrace.</div> <div>1</div> | |
| <div>Storm and coastal erosion events impacting on the creek/ drain at the northern end of Victoria Terrace with the risk of significant erosion into the open spinifex dune area directly north of the drain.</div> <div>2</div> | <div>Maintain cyclical / event based regime of maintenance works to rectify erosion at the creek/ drain located at the northern end of Victoria Terrace, Shelly Beach.</div> <div>2</div> | |
| <div>Open Spinifex coastal dune lacking overstorey vegetation to provide greater levels of dune stabilisation.</div> | | <div>Establishment of open /sparse plantings of Casuarina, Banksia and Pandanus from the fence line east to the mid-point on the dune. Planting to support dune stabilisation and contribute to light spill management. Spacings to allow for filtered views to the beach and ocean from the coastal path.</div> <div>3</div> |
| <div>Unapproved management (mowing) of public land on western side of coastal path.</div> | <div>Mowing / maintenance of the public open space to be undertaken by and in accordance with Council approved levels of service.</div> <div>4</div> | |
| <div>Vegetation (trees) reaching senescence, being removed, and not replaced from public open space.</div> | <div>Public open space vegetation / tree management regime to ensure replacement program of trees / vegetation to ensure retention of public amenity and shade.</div> <div>5</div> | |



Creek/drain at the northern end of Victoria Terrace

